MONSANTO

From:	K.W. Lichtenheld	cs6G	Corpor	ate Engineering	(4-6627)
Date:	August 12, 1985		cc: D.	.R. Bowers	CS6G
			L.	.V. Bumbicka	1740
Subj:	Project Progress	Meetings	R.	.M. Calles	CS6G
•			м.	A. Coco	Alberici
Re:	CEA 3808 - Main	South Trunk	Sewer R.	.J. Geile	CS6G
			E.	.R. Hartman	CS6G
TO:	J.J. Beckerle	Alberici	P.	.R. Hoemann	1740
	W. Bodine	Alberici	L.	.C. Kreh	F2ED
	T.N. Carrico	1740*	F.	A. Mayse	CS6G
	G.A. Grundmann	CS6G	В.	.W. Steketee	1740**
	W.C. Koester	Alberici*	R.	.L. Wiese	CS6G
	C.J. Lotz	Alberici			
	R.L. Nelson	1740*	*1	Present at meeting	1
	K.W. Petterson	1740*	**	Part time	
	R.C. Martini	1740*			
	O.N. Shipley	1740*			
	R. Schlereth	Fleischer	Seeger**		
	R.B. Knoll	Fleischer	Seeger		

Following are minutes of the meeting held at the CED construction trailers on 8/9/85 at 9:30 a.m.

1. Construction Progress

77.

- a. T-2 jumper installed.
- b. Excavation between manhole 2-AA & 2-EE and manhole 2-BB & 2-CC continues.
- c. "42" dia. VCP has been installed and cleaning up is being done between manhole 1-EE & 2-AA.
- d. Lateral L-45 pipe has been installed and encasement forms are being installed.
- e. Encasement poured between manhole 1-EE & 1-JJ.
- f. 42 VCP tested between manhole 1-EE & 2-AA. There were 3 leakers out of 18 joints. 4 joints had evidence of bubbling due to exotherm and this material will be ground out of the joint.
- g. Lateral L-35 was retested. Cracks are present in 2 pieces of VCP, in and adjacent to the bell.
- h. Test on manhole 1-GG. Some leaks in the windows were present and have been patched.

WGK 4084648

J.J. Beckerle, et al August 9, 1985 Page 2

- Poured manhole 2-AA and installed stub for lateral to the north.
- j. 24° dia. flume at manhole 2-AA to be installed as jumper T-l is being used to divert flow to the east.
- k. Additional grinding on manholes 1-BB & 1-CC was done at encasement to bring manholes into spec.
- Alberici has cost figure on tunnel crossing between manhole 3-AA & 3-BB.
- m. Alberici has cost estimate on joints to be redone due to exothermic damage.
- n. Manhole 1-AA has first step of furan lining installed.
- Manhole 1-BB. Asphalt membrane being applied after grinding of walls was accepted.
- p. Asphalt membrane. R. Schlereth stated that they were not having any problem with the high asphalt temperatures. They are maintaining kettle temperatures of 360°-400°F, with pouring temperatures at 360°F. They are also not having any asphalt running and dripping as before.

Contaminated Soil

- a. Still waiting for state permits to ship stockpiled material.
- b. <u>Petterson</u> to give Nelson quantities of earth to be landfilled that are stockpiled.

3. Jumpers

- a. The 21° dia. VCP for T-3 was ordered with extra fittings for possible changes.
- b. Investigation of undergrounds for this jumper is held up due to the presence of the MCB tank in the area. This work should get started about August 14.
- c. A discussion of the type of joint to be used for the jumpers ensued. <u>Lichtenheld</u> stated that his position has been as follows:

WGK 4084649

J.J. Beckerle, et al August 9, 1985 Page 3

- 1) Use the joint shown on the contract drawings.
- 2) Permission was given to JSA at their request to use Tamping Mix instead of the Tufchem II and at no additional cost to the project.
- 3) Use plain bell pipe (no gaskets).
- Use gasket supplied by Dicky on pipe and remove the gasket.
- 5) Joints 3 & 4 would require fully packed joints.

4. Dept. 245

- a. It has been decided to use a corrugated metal pipe under the gracks between manhole 3-AA & 3-BB. Petterson to get with JSA and determine length and get corrugated pipe on order.
- b. JSA indicated that 8 working days are required to install the corrugated pipe under the tracks.

5. VCP Joints

a. Koester agreed that JSA would flag Monsanto personnel on any future exothermic reaction causing boiling so that revised procedures and/or steps could be implemented to prevent this condition.

6. Miscellaneous

- a. It was pointed out that the specs call for sandblasting all surfaces of VCP where membranes lap onto pipe.
- b. A cost estimate on lateral L-85 under the tracks is due by JSA.
- c. Extra work will be required of JSA to meet housekeeping requirements for the plant inspection on October 1 & 2.
- d. Lichtenheld advised project members that he will be on vacation from 8/17 through 9/3/85.

The next progress meeting will be held on Thursday, August 15, at 9:30 a.m. at the construction trailers. All Monsanto project personnel are to meet prior to this meeting at 9:00 a.m.

K.W. Lichtenheld

ga/2178Z

HGK 4084650